aidacare lifecomfort

FALL SAFETY MAT

A Fall Safety Mat is designed to reduce the risk of injury, particularly the risk of head injury (*Bowers et al, 2008*), when a person rolls out of bed. The non-slip underside prevents accidental movement of the mat, whilst the reflective strip minimises the risk of tripping when used in low light. When not in use, it can be easily folded for convenient and compact storage.

Divided into sections to allow for convenient folding and storage

A reflective strip helps to prevent tripping by ensuring that the mat is visible to carers and residents in low light

A non-slip underside prevents unintentional movement of the mat by the carer or resident







Table 1. Head Impact Forces During Head-First Falls With and Without a Floor Mat

*Reference from; Bowers, B; Lloyd, J; Lee, W; Powell-Cope, G; Baptiste, A. 2008. Biomechanical Evaluation of Injury Severity Associated with Patient Falls from Bed. *Rehabilitation Nursing*. Vol. 33, no. 6, pp. 253-259.

Code	BEA008550
Description	Lifecomfort Fall Safety Mat
Length	1760mm
Width	600mm
Height	50mm
Warranty	12 months

www.aidacare.com.au | 1300 133 120



Parts B

PRESSURE SAFETY UNDERLAY

Specifically for use underneath an Alternating Pressure Overlay, the Aidacare LIFECOMFORT Pressure Safety Underlay is designed to provide 'bottoming out' protection while minimising the overall mattress height on the bed. The foam underlay can be rotated in four directions to maximise longevity and performance. It features a fully welded, CARRFlex Bi-Elastic cover.



EVACUATION SHEET

Designed for the emergency evacuation of the non-ambulant person, the Aidacare LIFECOMFORT Evacuation Sheet:

- Fits discreetly underneath the resident's mattress
- Allows bed making to occur as normal
- Remains readily accessible in case of emergency evacuation
- Is fire retardant and highly durable

The Evacuation Sheet was designed to help rescue teams, carers or nurses to slide the mattress and resident along any floor surface or even downstairs, increasing resident safety and preventing injury to nursing staff.

ABFY07.6 29061